

# **ENGINEERING CHANGE NOTIFICATION FORM**

ECN: 100-001-000123 REV: 1 ISSUE DATE: 12/18/2012

TYPE OF CHANGE: Firmware Modification

# DETAILED DESCRIPTION OF CHANGE:

Firmware improvements outlined in detail below.

# **REASON FOR CHANGE:**

Functionality Improvements and bug fixes.

# PRODUCTS AFFECTED:

RODOCIS ATTECTED.		
Firmware Version	Model	
Units with firmware version 0.928 and earlier	FireFly-1A	
	GPSTCXO/GPSOCXO	
	LC_XO	
	M9107/9108	

# **AVAILABILITY:**

MILESTONE	DATE
ECN sent to customer	12/21/2012

#### Issue:

NMEA sentences such as \$GPGGA may be missing a leading zero in the longitude output for longitudes less than +/-10 degrees. Longitudes greater or equal to +/-10 degrees are not affected. NMEA specifies a constant number of digits for longitude, and the missing leading zero may cause some application software to interpret the longitude incorrectly. The latitude output is properly formatted.

#### Cause:

The NMEA output format is incorrectly programmed by missing a leading zero in the longitude field for longitudes less than 10 degrees from Greenwich.

# Affected products:

FireFly-1A GPSTCXO/GPSOCXO LC\_XO M9107/9108

# Solution:

Upgrading affected units to firmware revision 0.929 will fix this issue.

# **REFERENCE DOCUMENTS/ATTACHMENTS:**

CONTACTS	NAME	EMAIL
Product Manager	Said Jackson	support@jackson-labs.com

