

ENGINEERING CHANGE NOTIFICATION FORM

ECN: 80200559	REV: 1	ISSUE DATE: 11/17/2017						
TYPE OF CHANGE: Firmware Modification								
DETAILED DESCRIPTION OF CHANGE: Firmware release 3.04 for Mini-JLT GNSS for bug fixes.								
REASON FOR CHANGE: Bug fixes.								
PRODUCTS AFFECTED: <table border="1" data-bbox="131 688 1458 762"> <thead> <tr> <th>Firmware Version</th> <th>Model</th> </tr> </thead> <tbody> <tr> <td>Firmware 3.01 version</td> <td>Mini-JLT GNSS</td> </tr> </tbody> </table>			Firmware Version	Model	Firmware 3.01 version	Mini-JLT GNSS		
Firmware Version	Model							
Firmware 3.01 version	Mini-JLT GNSS							
Notes:								
AVAILABILITY: <table border="1" data-bbox="131 821 1458 888"> <thead> <tr> <th>MILESTONE</th> <th>DATE</th> </tr> </thead> <tbody> <tr> <td>ECN release for firmware release files</td> <td>11/17/2017</td> </tr> </tbody> </table>			MILESTONE	DATE	ECN release for firmware release files	11/17/2017		
MILESTONE	DATE							
ECN release for firmware release files	11/17/2017							
Release 3.04 for Mini-JLT GNSS provides the following improvement: Issue 1: uBlox receivers modified the GPS version command so it could no longer be read by the Mini-JLT GNSS. Units already in the field would not be affected. Units already in the field are not affected since this v3.04 is applied at the factory to units requiring the update. Resolution: Firmware 3.04 modifies the GPS message handling to support the modified GPS version command.								
REFERENCE DOCUMENTS/ATTACHMENTS: <table border="1" data-bbox="131 1402 1458 1512"> <thead> <tr> <th>CONTACTS</th> <th>NAME</th> <th>EMAIL</th> </tr> </thead> <tbody> <tr> <td>Software Engineer</td> <td>Keith Loiselle</td> <td>keith@jackson-labs.com</td> </tr> </tbody> </table>			CONTACTS	NAME	EMAIL	Software Engineer	Keith Loiselle	keith@jackson-labs.com
CONTACTS	NAME	EMAIL						
Software Engineer	Keith Loiselle	keith@jackson-labs.com						

PLEASE CONTACT JACKSON LABS TECHNOLOGIES, INC. WITH ANY QUESTIONS