

ENGINEERING CHANGE NOTIFICATION FORM

ECN: 80200575	REV: 1	ISSUE DATE: 4/17/2019						
TYPE OF CHANGE: Firmware Modification								
DETAILED DESCRIPTION OF CHANGE: Firmware release 3.06 for Mini-JLT GNSS for bug fixes and fine tuning of configuration for units at factory of Jackson Labs only.								
REASON FOR CHANGE: Bug fixes and functionality improvements.								
PRODUCTS AFFECTED: <table border="1" data-bbox="126 688 1458 762"> <thead> <tr> <th>Firmware Version</th> <th>Model</th> </tr> </thead> <tbody> <tr> <td>Firmware 3.05 and previous</td> <td>Mini-JLT GNSS</td> </tr> </tbody> </table>			Firmware Version	Model	Firmware 3.05 and previous	Mini-JLT GNSS		
Firmware Version	Model							
Firmware 3.05 and previous	Mini-JLT GNSS							
Notes:								
AVAILABILITY: <table border="1" data-bbox="126 821 1458 888"> <thead> <tr> <th>MILESTONE</th> <th>DATE</th> </tr> </thead> <tbody> <tr> <td>ECN release for firmware release files</td> <td>4/17/2019</td> </tr> </tbody> </table>			MILESTONE	DATE	ECN release for firmware release files	4/17/2019		
MILESTONE	DATE							
ECN release for firmware release files	4/17/2019							
Release 3.06 for Mini-JLT GNSS provides the following improvements: Issue 1: The OCXO Current field of SYSTem:STATus? command reports FAILED due to the absence of current measurement sensor in firmware version 3.05. Resolution: Firmware 3.06 corrects the issue by disabling the OCXO current check for Mini-JLT GNSS unit with no current sensor.								
REFERENCE DOCUMENTS/ATTACHMENTS: <table border="1" data-bbox="126 1310 1458 1417"> <thead> <tr> <th>CONTACTS</th> <th>NAME</th> <th>EMAIL</th> </tr> </thead> <tbody> <tr> <td>Software Engineer</td> <td>Yun Lan</td> <td>yun@jackson-labs.com</td> </tr> </tbody> </table>			CONTACTS	NAME	EMAIL	Software Engineer	Yun Lan	yun@jackson-labs.com
CONTACTS	NAME	EMAIL						
Software Engineer	Yun Lan	yun@jackson-labs.com						

PLEASE CONTACT JACKSON LABS TECHNOLOGIES, INC. WITH ANY QUESTIONS